



POWER TOOLS



PVC



VAND
+60°C

D1	D	L	Farve	Tryk	Hætte	
3/8" = 10	16	50 m	Blå	15 BAR	16	
1/2" = 12	19	50 m	Blå	15 BAR	20	
3/8" = 10	16	50 m	Rød	15 BAR	16	
1/2" = 12	19	50 m	Rød	15 BAR	20	
3/8" = 10	16	50 m	Transparent	15 BAR	16	
1/2" = 12	19	50 m	Transparent	15 BAR	20	


EPDM



VAND
+160°C

D1	D	L	Farve	Tryk	Hætte	
3/8" = 10	17	50 m	Blå	20 BAR	17,5	
1/2" = 13	21	50 m	Blå	20 BAR	21	
3/8" = 10	17	50 m	Rød	20 BAR	17,5	
1/2" = 13	21	50 m	Rød	20 BAR	21	
3/8" = 10	17	50 m	Sort	20 BAR	17,5	
1/2" = 13	21	50 m	Sort	20 BAR	21	


NBR



VAND / OLIE

D1	D	L	Farve	Tryk	Hætte	
3/8" = 10	17	50 m	Sort	20 BAR	17,5	
1/2" = 13	21	50 m	Sort	20 BAR	23	

SILICONE



VAND
+170°C

D1	D	L	Farve	Tryk	Hætte	
3/8" = 10	14	25 M	Rustfri flet	15 BAR	16	
1/2" = 12	17	25 M	Rustfri flet	15 BAR	20	